

SOURCE UTILIZATION REPORT FORM

Isotope: ³²P Licensee: _____ Licensee No: _____ RSO# _____

Compound: ATP, Redivue

Receipt Date: 04/19/1999 Starting Amount (mCi) 0.50000

Date Used	Activity Used	Activity Remaining	Used Activity Disposal			Post Use Contamination Survey			
			Solid	Liquid	Scint vials	Max, CPM	Location	Decon (Y,N,NA)	Initial
[A] 4/19/99	0.05	0.45	0.025	0.025	—	<50	N/A	N/A	ae
[B] 4/20/99	0.05	0.4	0.025	0.025	-	50k	CENT-RIFUGE	y	ae
[C] 4/20/99	0.05	0.35	0.025	0.025	0.001	100k	Blotter Paper	y	ae

1. Use this log to maintain a current inventory of radioactive material in your laboratory.
2. Return this form to the Office of Radiation Safety when the source is depleted/disposed, to ensure it is removed from inventory records.
3. Procedures for "User Surveys" are found in section 4.3.2 of the ASU Radioactive Materials Manual. Work areas must, at a minimum, be surveyed for contamination each day unsealed sources of radioactive material are used, and surveys must be documented.

Source Depleted/Disposal:

Licensee (or designate) signature Printed Name Date

Removed from Inventory:
Date: _____ Init: _____
(ORS only)